







Air Quality



AES Argentina
October 2025







Saavedra Air Quality Monitoring Station



No values exceeding the permitted limit were detected



San Nicolás Thermal Power Plant



No values exceeding the permitted limit were detected

